PRODUCTS: D975XBX2 (Standard BIOS)

BIOS Version 2431

About This BIOS:
- January 11, 2007
- BX97520J.86A.2431.2007.0110.1629
- SATA RAID info:
    - Intel(R) RAID for SATA - v5.6.2.1002
    - Marvell 88SE6145 SATA BIOS – v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
    - Intel® AMT BX Firmware: v1.2.3

New Fixes/Features:
- Added Hardware Watchdog Timer feature
- Fixed display of L2 Cache in BIOS Setup for multi-core processors
- Added "HPET Enable/Disable" BIOS setup option and set default state to "Disable"
- Fixed calculation and display of the nominal (TCL-TRCD-TRP-TRASMin) memory timing values in BIOS Setup
- Fixed issue where certain processors would not resume from standby

---

BIOS Version 2395

About This BIOS:
- December 20, 2006
- BX97520J.86A.2395.2006.1220.1100
- SATA RAID info:
    - Intel(R) RAID for SATA - v5.6.2.1002
    - Marvell 88SE6145 SATA BIOS – v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
    - Intel® AMT BX Firmware: v1.2.3

New Fixes/Features:
- Added feature to always display the latest event's date and time of event log.
- Fixed a problem where the system would boot to the wrong boot device in AHCI or RAID mode.
- Fixed a problem where the setup option for Floppy did not display correctly.
- Fixed the potential issue where all fans are on 100% when CPU is changed.
- Fixed the display alignment of the output values on the BIOS setup hardware monitoring page.

*Other names and brands may be claimed as the property of others.

- Fixed the display of negative value on BIOS setup Hardware Monitoring Page with some CPUs.
- Added work-around for IDE-R 6 hour open session issue in a host software package.
- Fixed system continues to boot to next bootable device when no IDER media present during AMT IDER & SOL session.
- Fixed issue where POST errors may be displayed during Maintenance Mode boot.
- Fixed issue where system hangs after AC Loss if the Reference Frequency is overridden.
- Hide "Clear TPM" option in Maintenance setup page if TPM is not enabled or not supported.
- Fixed issue where Intel® Audio Studio does not launch with 3GB Memory and certain PCI-E video card.
- Removed USB 2.0 Enable/Disable question from setup.
- Fixed AMT system only able to provision when USB device is present.
- Fixed issue where TPM Physical Presence was not cleared and locked intermittently at the end of POST.
- Added fix to eliminate fan speed surge after reset.
- Fixed issue where Vista would hang during boot on systems with Atmel TPM if the TPM was enabled in BIOS SETUP.
- New PXE Base code : Intel(R) Boot Agent GE v1.2.42

BIOS Version 2333

About This BIOS:
- November 27, 2006
- BX97520J.86A.2333.2006.1127.1450
- SATA RAID info:
  - Intel(R) RAID for SATA – v5.6.2.1002
  - Marvell* 88SE6145 SATA BIOS – v1.1.0.34
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

New Fixes/Features:
- Fixed issue where ICH7 controller would not come up in the proper mode in certain circumstances.

BIOS Version 2330

About This BIOS:
- November 16, 2006
- BX97520J.86A.2330.2006.1116.1034
- SATA RAID info:
  - Intel(R) RAID for SATA – v5.6.2.1002
  - Marvell* 88SE6145 SATA BIOS – v1.1.0.34
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

New Fixes/Features:
- Fixed issue where "Clear BIOS Passwords" feature in Maintenance Page of BIOS Setup was not working.
- Updated Marvell* 88SE6145 Option ROM to version 1.1.0.34.

*Other names and brands may be claimed as the property of others.

- Fixed issue where BIOS Setup defaults would overwrite current user settings when entering Maintenance Mode.
- Added Microsoft* Vista* support for STAC9227 and STAC9274D audio codecs.
- Expanded overclocking functionality.
- Added IDCC version 2.02 support.
- Fixed an issue where auto-recovery from a corrupt image wasn't working.
- Fixed fan speed surge during initial power on.
- Fixed higher than normal Fan noise with certain processors.
- Fixed potential issue where Fan speed stuck at 100%.
- Fixed issue where attempting to use the One Time Boot Menu appeared to hang POST.
- Fixed issue where Recovery status screen is blank.

BIOS Version 2214

About This BIOS:
- October 23, 2006
- BX97520J.86A.2214.2006.1023.1710
- SATA RAID info:
    - Intel(R) RAID for SATA – v5.6.2.1002
    - Marvell* 88SE6145 SATA BIOS – v1.1.0.17
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
    - Intel® AMT BX Firmware: v1.2.3

New Fixes/Features:
- Fixed issue where Marvell* SATA Controller is Disabled by default on first board boot.

BIOS Version 2212

About This BIOS:
- October 21, 2006
- BX97520J.86A.2212.2006.1021.1659
- SATA RAID info:
    - Intel(R) RAID for SATA – v5.6.2.1002
    - Marvell* 88SE6145 SATA BIOS – v1.1.0.17
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
    - Intel® AMT BX Firmware: v1.2.3

New Fixes/Features:
- Improved overclocking headroom in some cases.
- Fixed potential POST hang.
- Fixed intermittent hang when margining the host clock.
- Supports OEM Activation 2.0. For details on the OEM Activation Program, send email to oasignh@microsoft.com
- Fixed the corrupted display which shows incorrect digits of RPM for fans when they are stopped.
- Fixed PCIe frequency margining not working in some cases.
- Fixed issue where S3 did not work with certain processors.
- Fixed issue where operating system installation would blue screen with certain processors.

```
BIOS Version 1846
```

About This BIOS:
- September 29, 2006
- BX97520J.86A.1846.2006.0929.0913
- SATA RAID info:
    - Intel(R) RAID for SATA – v5.6.2.1002
    - Marvell* 88SE6145 SATA BIOS – v1.1.0.17
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
    - Intel® AMT BX Firmware: v1.2.3

New Fixes/Features:
- Initial production bios release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a registered trademark of Intel Corporation.
Copyright (c) 2006 Intel Corporation.