

BIOS Update Release Notes

PRODUCTS: DQ57TM (Standard BIOS)

BIOS Version 0029 - TMIBX10H.86A.0029.2010.0203.1403

About This Release:

- February 3, 2010
- Integrated Graphics Option ROM Revision: 1973 PC 14.34
- PXE LAN Option ROM Revision: PXE 2.1 Build 086, v1.3.40
- SATA RAID Option ROM Revision: 9.5.0.1037
- ME Firmware: 8MB SKU 6.0.30.1203
- MEBx Code: Based on Version 6.0.3.0019

New Fixes/Features:

- Fixed issue where installing Windows XP* over the network fails without keyboard.
- Fixed issue with onboard LAN item displaying incorrectly with AMT enable\disable in MEBx.
- Updated vBIOS to version 1973.
- Fixed ECC Event logging failure with certain processors.
- Fixed issue related to hard disk password.
- Fixed issue where monitor does not remain in sleep state when waking system from S1, S3.
- Fixed issue where external SATA port cannot be disabled in AHCI and RAID mode.
- Fixed issue where onboard LAN and Intel® ME fails after an Express BIOS Update.
- Added support for NTFS file system in BIOS Flash menu (F7).
- Hid Performance page for Intel® Integrator Toolkit (ITK).
- Changed SMBIOS type10 onboard device name string of IGD.
- Implemented Security Phase 1 & 2.
- Fixed issue where 3rd party RAID card shows an initialization error.
- Updated QST payload to 1228.
- Updated Intel® ME firmware to production version 1203.
- Fixed issue where iAMT Web GUI is missing media information.
- Disabled hard disk password in RAID mode.
- Improved the WARNING message on "Reset Intel AMT to default factory settings" in EFI MEBx.
- Corrected string "Resetting Intel(R) AMT in progress..." in Maintenance Mode.
- Added a global reset after flash update.
- Fixed issue where BIOS fails to report watchdog timeout to ME event log.
- Fixed trailing spaces on System Manufacturer field.

BIOS Version 0025 - TMIBX10H.86A.0025.2009.1202.2128

About This Release:

• December 02, 2009

- Integrated Graphics Option ROM Revision: 1931 PC 14.34
- PXE LAN Option ROM Revision: PXE 2.1 Build 086, v1.3.40
- SATA RAID Option ROM Revision: 9.5.0.1037
- ME Firmware: 8MB SKU 6.0.2.1194
- MEBx Code: Based on Version 6.0.3.0019

New Fixes/Features:

• Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries. Copyright (c) 2009 Intel Corporation.