



## BIOS Update Release Notes

### PRODUCTS: D975XBX2 (Standard BIOS)

#### BIOS Version 2747

##### About This BIOS:

- May 23, 2007
- BX97520J.86A.2747.2007.0523.1129
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell 88SE6145 SATA BIOS - v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

##### New Fixes/Features:

- Updated processor support.
- Updated the Heceta6 Voltage conversion constants.
- Fixed an issue where with certain processor fan goes 100%.
- Fixed S3 wake-up fails when drives are attached to Marvell\* RAID controller.
- Fixed PXE always attempts to load when drives are attached to Marvell\* controller.
- Fixed audio Code subsystem ID problem after resuming S3.

#### BIOS Version 2692

##### About This BIOS:

- April 03, 2007
- BX97520J.86A.2692.2007.0403.1844
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell 88SE6145 SATA BIOS - v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

##### New Fixes/Features:

- Updated processor support.

#### BIOS Version 2674

##### About This BIOS:

- March 15, 2007
- BX97520J.86A.2674.2007.0315.1546
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002

\*Other names and brands may be claimed as the property of others.

- Marvell 88SE6145 SATA BIOS - v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Fixed failures with the TCG ACPI Event Log when running the Vista DTM TCG TPM BIOS Interface Test.
- Fixed issue where system would hang booting Windows XP with OEM Activation 2.0 data programmed, EIST enabled, and certain processor installed in the system.
- Modified IRQ table to evenly distribute IRQs for devices.
- Fixed priority issue in Advance Boot Mode when Legacy Floppy is installed without a media.

<b>BIOS Version 2663</b>
--------------------------

**About This BIOS:**

- March 05, 2007
- BX97520J.86A.2663.2007.0305.1750
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell 88SE6145 SATA BIOS - v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Updated processor support.
- Fixed a problem where Setup F9 key caused unexpected page movement at submenu option.
- Fixed a missing highlight cursor problem in Setup after pressing F10 and no response.
- Fixed Setup cosmetic issue where garbage characters are printed outside of string input box.
- Fixed F10 boot menu showing two lines of duplicated title.
- Added AMT1.0 support for certain SKUs.
- Fix POST hang when SATA Controller is set to disable and IDE/ATA Mode is set to legacy mode.
- Fixed issue where certain host adapter cards not functional.
- Added support for loading the Microsoft Windows Vista\* native TPM 1.2 driver.
- Fixed yellow bang in Windows XP\* Device Manager for the TPM 1.2 device.

<b>BIOS Version 2634</b>
--------------------------

**About This BIOS:**

- February 16, 2007
- BX97520J.86A.2634.2007.0216.1057
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell 88SE6145 SATA BIOS - v1.1.0.34

\*Other names and brands may be claimed as the property of others.

- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Added support for ACPI Serial Port Console Redirection (SPCR) table for AMT SOL.
- Added support for Windows Vista\* Media Center OCUR Host Firmware Support.
- Added fix for ITK where Parallel Port is always hidden.
- Added fix for Windows Vista\* where EBIOSPost.exe had error while returning EBU status.

<b>BIOS Version 2618</b>
--------------------------

**About This BIOS:**

- February 12, 2007
- BX97520J.86A.2618.2007.0212.0954
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell 88SE6145 SATA BIOS - v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Updated Microsoft Vista\* support for STAC9227 and STAC9274D Audio Codecs.
- Fixed boot order for SCSI HDD with certain SCSI controllers.
- Adding Serial Port enable/disable setup question in Standard BIOS.
- Added programming of PCI Subsystem Vendor ID and Subsystem ID for the PCIe Graphics bridge.
- Fixed issue where system would not boot after installing a Vista\* OEM Activation string.
- Fixed issue where certain host bus adapter card was not functional.
- Added code to program the OEM SVID and SSID for onboard Marvell\* controller.
- Reduced S3 resume time related to processor detection.
- Fixed issue where 64-bit operating system installs would blue screen with certain processors.

<b>BIOS Version 2507</b>
--------------------------

**About This BIOS:**

- January 23, 2007
- BX97520J.86A.2507.2007.0123.0952
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell\* 88SE6145 SATA BIOS - v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:

\*Other names and brands may be claimed as the property of others.

- Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Fixed issue where ECC Mode was not properly displayed when Performance Memory Profiles set to Manual in BIOS Setup.
- Added workaround for HDD LED always being lit when Secondary SATA Controller is disabled in BIOS Setup.
- Fixed boot order for add-in SCSI controller.
- Added support for certain SAS controller.
- IRQ Fix for USB Interrupts.
- Fixed failures seen with Vista\* DTM BitLocker Drive Encryption BIOS Interface Logo Test.
- Fixed issue where Microsoft\* Vista BitLocker System Check would not pass.
- Fixed issue where system would not recognize CTRL+ALT+DEL key sequence from boot cycling machine.
- Fixed failures with the TCG ACPI Event Log when running the Vista DTM TCG TPM BIOS Interface Test.
- Fixed issue where system hangs when trying to load FreeDOS\* bootable CD from a USB CD drive.
- Fixed ACPI failures when running the Vista DTM TCG TPM Integration Test.

<b>BIOS Version 2431</b>
--------------------------

**About This BIOS:**

- January 11, 2007
- BX97520J.86A.2431.2007.0110.1629
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell 88SE6145 SATA BIOS - v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Added Hardware Watchdog Timer feature
- Fixed display of L2 Cache in BIOS Setup for multi-core processors
- Added "HPET Enable/Disable" BIOS setup option and set default state to "Disable"
- Fixed calculation and display of the nominal (TCL-TRCD-TRP-TRASMin) memory timing values in BIOS Setup
- Fixed issue where certain processors would not resume from standby

<b>BIOS Version 2395</b>
--------------------------

**About This BIOS:**

- December 20, 2006
- BX97520J.86A.2395.2006.1220.1100
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell 88SE6145 SATA BIOS - v1.1.0.34
- PXE UNDI: Initializing Intel(R) Boot Agent GE v1.2.28
- PXE Base Code: Intel(R) Boot Agent GE v1.2.42

\*Other names and brands may be claimed as the property of others.

- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Added feature to always display the latest event's date and time of event log.
- Fixed a problem where the system would boot to the wrong boot device in AHCI or RAID mode.
- Fixed a problem where the setup option for Floppy did not display correctly.
- Fixed the potential issue where all fans are on 100% when CPU is changed.
- Fixed the display alignment of the output values on the BIOS setup hardware monitoring page.
- Fixed the display of negative value on BIOS setup Hardware Monitoring Page with some CPUs.
- Added work-around for IDE-R 6 hour open session issue in a host software package.
- Fixed system continues to boot to next bootable device when no IDER media present during AMT IDER & SOL session.
- Fixed issue where POST errors may be displayed during Maintenance Mode boot.
- Fixed issue where system hangs after AC Loss if the Reference Frequency is overridden.
- Hide "Clear TPM" option in Maintenance setup page if TPM is not enabled or not supported.
- Fixed issue where Intel® Audio Studio does not launch with 3GB Memory and certain PCI-E video card.
- Removed USB 2.0 Enable/Disable question from setup.
- Fixed AMT system only able to provision when USB device is present.
- Fixed issue where TPM Physical Presence was not cleared and locked intermittently at the end of POST.
- Added fix to eliminate fan speed surge after reset.
- Fixed issue where Vista would hang during boot on systems with Atmel TPM if the TPM was enabled in BIOS SETUP.
- New PXE Base code : Intel(R) Boot Agent GE v1.2.42

<b>BIOS Version 2333</b>
--------------------------

**About This BIOS:**

- November 27, 2006
- BX97520J.86A.2333.2006.1127.1450
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell\* 88SE6145 SATA BIOS - v1.1.0.34
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Fixed issue where ICH7 controller would not come up in the proper mode in certain circumstances.

<b>BIOS Version 2330</b>
--------------------------

\*Other names and brands may be claimed as the property of others.

**About This BIOS:**

- November 16, 2006
- BX97520J.86A.2330.2006.1116.1034
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell\* 88SE6145 SATA BIOS - v1.1.0.34
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Fixed issue where "Clear BIOS Passwords" feature in Maintenance Page of BIOS Setup was not working.
- Updated Marvell\* 88SE6145 Option ROM to version 1.1.0.34.
- Fixed issue where BIOS Setup defaults would overwrite current user settings when entering Maintenance Mode.
- Added Microsoft\* Vista\* support for STAC9227 and STAC9274D audio codecs.
- Expanded overclocking functionality.
- Added IDCC version 2.02 support.
- Fixed an issue where auto-recovery from a corrupt image wasn't working.
- Fixed fan speed surge during initial power on.
- Fixed higher than normal Fan noise with certain processors.
- Fixed potential issue where Fan speed stuck at 100%.
- Fixed issue where attempting to use the One Time Boot Menu appeared to hang POST.
- Fixed issue where Recovery status screen is blank.

**BIOS Version 2214****About This BIOS:**

- October 23, 2006
- BX97520J.86A.2214.2006.1023.1710
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell\* 88SE6145 SATA BIOS - v1.1.0.17
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Fixed issue where Marvell\* SATA Controller is Disabled by default on first board boot.

**BIOS Version 2212****About This BIOS:**

- October 21, 2006
- BX97520J.86A.2212.2006.1021.1659
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell\* 88SE6145 SATA BIOS - v1.1.0.17
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:

\*Other names and brands may be claimed as the property of others.

- Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Improved overclocking headroom in some cases.
- Fixed potential POST hang.
- Fixed intermittent hang when margining the host clock.
- Supports OEM Activation 2.0. For details on the OEM Activation Program, send email to oasighn@microsoft.com
- Fixed the corrupted display which shows incorrect digits of RPM for fans when they are stopped.
- Fixed PCIe frequency margining not working in some cases.
- Fixed issue where S3 did not work with certain processors.
- Fixed issue where operating system installation would blue screen with certain processors.

<b>BIOS Version 1846</b>
--------------------------

**About This BIOS:**

- September 29, 2006
- BX97520J.86A.1846.2006.0929.0913
- SATA RAID info:
  - Intel(R) RAID for SATA - v5.6.2.1002
  - Marvell\* 88SE6145 SATA BIOS - v1.1.0.17
- Initializing Intel(R) Boot Agent GE v1.2.28
- Intel® Active Management Technology info:
  - Intel® AMT BX Firmware: v1.2.3

**New Fixes/Features:**

- Initial production bios release

---

---

**LEGAL INFORMATION**

---

---

**Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.**

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a registered trademark of Intel Corporation.  
Copyright (c) 2006 Intel Corporation.

\*Other names and brands may be claimed as the property of others.