



BIOS Update Release Notes

PRODUCTS: DG43GT (Standard BIOS)

BIOS Version 0031 - GTG4310H.86A.0031.2010.0406.1752

About This Release:

- April 06, 2010
- ME Firmware: 5.2.0.1002
- MEBx Code: Based on Version 5.0.5.0004
- Integrated Graphics Option ROM: Build 2011 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent v1.3.38 IBA GE Slot 00C8 v1338
PXE Base Code (PXE-2.1 build 088)

New Fixes/Features:

- Updated VBIOS Build Number to 2011 PC 14.34

New Fixes/Features:

- Fixed issue where BIOS Setup is inconsistent on memory.
- Fixed intermittent issue where operating system boot screen appears scrambled.
- Fixed issue where USB device causes lookup in Pre-Windows* environment.
- Set Flex module minimum space 60kB.
- S3 resume less than 2 second.
- Added support for AHCI mode.

BIOS Version 0029 - GTG4310H.86A.0029.2010.0225.2003

About This Release:

- February 25, 2010
- ME Firmware: 5.2.0.1002
- MEBx Code: Based on Version 5.0.5.0004
- Integrated Graphics Option ROM: Build 1985 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent v1.3.38 IBA GE Slot 00C8 v1338
PXE Base Code (PXE-2.1 build 088)

New Fixes/Features:

- Updated ME F/W version to 5.2.0.1002
- Updated VBIOS version to 1985 PC 14.34

BIOS Version 0028 - GTG4310H.86A.0028.2010.0108.1147

About This Release:

- January 08, 2010
- ME Firmware: 5.0.2.1129
- MEBx Code: Based on Version 5.0.5.0004
- Integrated Graphics Option ROM: Build 1800 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent v1.3.38 IBA GE Slot 00C8 v1338
PXE Base Code (PXE-2.1 build 088)

*Other names and brands may be claimed as the property of others.

New Fixes/Features:

- Fixed QST update configuration issue.
- Implemented security phase 2 features.
- Modified feature where user can't press Ctrl+Alt+Del to reset system with invalid password.
- Set VT item to be enabled by default.
- Fixed issue where system can't wake from S4 when "wake on Lan in S5" is set to disable.
- Updated chassis intrusion feature so password prompt is required.
- Updated PXE ROM version to 1.3.38
- Removed floppy configuration and PAVP Mode from .ITK file.
- Added feature where BIOS Supervisor password (if set) is required to downgrade a BIOS to a previous version.
- Added feature when updating the same QST Configuration payload for second time, it should show "Configuration has successfully delivered to QST".
- Fixed issue when user password user access level are set, F10 and F12 function still can work.
- Updated QST payload value, Modify TemperatureLimit value from - 5.00 to 0.00.

BIOS Version 0027 - GTG4310H.86A.0027.2009.1218.1048

About This Release:

- December 18, 2009
- ME Firmware: 5.0.2.1129
- MEBx Code: Based on Version 5.0.5.0004
- Integrated Graphics Option ROM: Build 1800 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent v1.3.31 IBA GE Slot 00C8 v1331
PXE Base Code (PXE-2.1 build 086)

New Fixes/Features:

- Removed iFlash2 non-reboot feature.
- Fixed issue where system S3 fails.
- Fixed QST Configuration issue when running QSTBIOS -W command.
- Removed HDD password function.
- Modified chassis fan detection behavior.
- Updated QST default payload value.
- Modified default value of fan detection.

BIOS Version 0024

About This Release:

- September 21, 2009
- GTG4310H.86A.0024.2009.0921.1022
- ME Firmware: 5.0.2.1129
- MEBx Code: Based on Version 5.0.5.0004
- Integrated Graphics Option ROM: Build 1800 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent v1.3.31 IBA GE Slot 0000 v1331
PXE Base Code (PXE-2.1 build 086)

New Fixes/Features:

- Fixed issue where Flex module is missing from .ITK file.
- Fixed issue where system will show "monitor not found" when using certain VGA cards.
- Fixed issue with VRM noise.

*Other names and brands may be claimed as the property of others.

BIOS Version 0022

About This Release:

- August 26, 2009
- GTG4310H.86A.0022.2009.0826.1219
- ME Firmware: 5.0.2.1129
- MEBx Code: Based on Version 5.0.5.0004
- Integrated Graphics Option ROM: Build 1800 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent v1.3.31 IBA GE Slot 0000 v1331
PXE Base Code (PXE-2.1 build 086)

New Fixes/Features:

- Fixed issue where system will show "monitor not found" when using certain VGA card.

BIOS Version 0021

About This Release:

- August 04, 2009
- GTG4310H.86A.0021.2009.0804.1759
- ME Firmware: 5.0.2.1129
- MEBx Code: Based on Version 5.0.5.0004
- Integrated Graphics Option ROM: Build 1800 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent v1.3.31 IBA GE Slot 0000 v1331
PXE Base Code (PXE-2.1 build 086)

New Fixes/Features:

- Set default of fan detection to Disable.
- Updated Video BIOS to version 1800.
- Modified on-board devices string of SMBIOS.
- Implemented iQST feature.
- Implemented updates to improve security.
- Fixed issue where system BIOS doesn't display splash screen after input of user password.

BIOS Version 0019

About This BIOS:

- June 25, 2009
- GTG4310H.86A.0019.2009.0625.1334
- ME Firmware: 5.0.2.1129
- MEBx Code: Based on Version 5.0.5.0004
- Integrated Graphics Option ROM: Build 1760 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent v1.3.31 IBA GE Slot 0000 v1331
PXE Base Code (PXE-2.1 build 086)

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2008 Intel Corporation.