

BIOS Update Release Notes

PRODUCTS: DQ87PG (Standard BIOS)

BIOS Version 0036 - PGQ8710H.86A.0036.2013.0702.1908

About This Release:

• Date: July 2, 2013

• Visual BIOS: 2.0.23 Production Candidate Build

• ME Firmware: 9.0.2.1345

• Integrated Graphics

Option ROM: Build 2170 PC 14.34

UEFI Driver: 5.0.1025

• LAN

Option ROM: v1403 PXE 2.1 Build 091

UEFI Driver: 5.1.00

• SATA RAID Option ROM: v12.0.0.1783

• MEBx Code: Based on Version 9.0.0.0023

New Fixes/Features:

• Fixed issue where Cooling Assistant does not work in Visual BIOS.

- Fixed issue with SATA port display string in Boot menu.
- Fixed issue where Graphics Voltage Target Multiplier (V) item should be removed.
- Fixed issue where USB3.0 hard drives can be detected when all USB3.0 ports are set to "No detect".
- Fixed WHQL issues for SMBIOS HCT and USB Exposed Port System Test.

BIOS Version 0035 - PGQ8710H.86A.0035.2013.0606.1800 Released

About This Release:

• Date: June 6, 2013

• Visual BIOS: 2.0.23 Production Candidate Build

• ME Firmware: 9.0.2.1345

Integrated Graphics

Option ROM: Build 2170 PC 14.34

UEFI Driver: 5.0.1025

• LAN

Option ROM: v1403 PXE 2.1 Build 091

UEFI Driver: 5.1.00

- SATA RAID Option ROM: v12.0.0.1783
- MEBx Code: Based on Version 9.0.0.0023

New Fixes/Features:

- Fixed issue where custom logo is not kept after BIOS recovery.
- Fixed issue where logo will not display during Recovery.
- Fixed issue where if Hard Drive Password Prompt is disabled, BIOS will never prompt for a Hard Drive password unless attempting to boot to a drive with a User Hard Drive Password installed.
- Added BIOS Recovery beep support.

^{*}Other names and brands may be claimed as the property of others.

- Fixed issue where boot priority in UEFI mode is changed after rebooting from the operating system.
- Added support to use ITK Custom Boot Order as the Default Boot Order
- Fixed BIOS Config Menu display strings when secure jumper is removed.
- Fixed the F3 Disable Fast boot function when the Power Button menu is displayed.
- Fixed the unsupported password key character warning beep.
- Updated Visual BIOS to version 2.0.23.
- Updated processor support.
- Fixed issue where Cooling Assistant does not work in Visual BIOS.
- Fixed issue with screen capture in Visual BIOS.
- Fixed issue where there is no illustration for the back panel.
- Fixed issue where some items display abnormally in ITK 5.0.
- Fixed SMBIOS DIMM information.
- Changed Setup item string [C6/C7 C-state] to [Lowest CPU Idle Power Setting].
- Added XTU improvement.
- Fixed issue where IGD Primary Video output shows incorrectly under UEFI only mode.
- Fixed IGD Minimum Memory issue.
- Fixed issue with Internal UEFI Shell.
- Fixed issue where HDD Passwords are still required when setting disabling Hard Disk Drive Password Prompt.
- Modified PCH deep S4/S5.
- Fixed issue where LEDs have the different state as when the platform is in S3.
- Fixed issue where the SATA Ports' location shown in "SATA Devices" does not match the board.
- Added Ctrl+P display and setup item.
- Changed the default value of POST Code Routing item to LPC Debug Header.
- Fixed issue where switching to text BIOS setup does not work with SOL.
- \bullet Fixed issue where PCI LAN card cannot wake system from S3, S4.
- Fixed issue where PCI modem cannot wake system from S3.
- Implemented C6/C7 C-state support.
- Added support for PCH deep S4/S5.
- Fixed issue with Active Processor Cores.
- Fixed issue with HDD password length.

PGQ8710H.86A.0030.2013.0403.1355 Released Candidate BIOS

About This Release:

• Date: April 3, 2013

• Visual BIOS: 2.0.17 Beta Build

• ME Firmware: 9.0.1.1345

• Integrated Graphics

Option ROM: Build 2170 PC 14.34

UEFI Driver: 5.0.1025

• LAN

Option ROM: v1403 PXE 2.1 Build 091

UEFI Driver: 5.1.00

^{*}Other names and brands may be claimed as the property of others.

- SATA RAID Option ROM: v12.0.0.1783
- MEBx Code: Based on Version 9.0.0.0023

New Fixes/Features:

• Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries. Copyright (c) 2013 Intel Corporation.

^{*}Other names and brands may be claimed as the property of others.