

**BIOS Update Release Notes** 

# PRODUCTS: DQ67SW, DQ67OW, DQ67EP (Standard BIOS)

# BIOS Version 0049 - SWQ6710H.86A.0049.2011.0314.1053

#### About This Release:

- March 14, 2011
- ME Firmware: 5MB SKU 7.1.10.1065 Production
- MEBx Code: Based on Version 7.0.0.0053
- Integrated Graphics Option ROM: Build 2108 PC 14.34
- SATA RAID Option ROM: Intel(R) RAID for SATA v10.1.0.1008
- LAN Option ROM: Intel(R) Boot Agent GE v1.3.65

#### New Fixes/Features:

- Updated Intel® ME F/W to version 7.1.10.1065.
- Updated VBIOS to version 2108.
- Fixed issue where Intel® Desktop Utilities displays no data when UEFI Boot is enabled.
- Updated "Boot Device Restoration" in HyperBoot.
- Fixed issue where S3 resume fails in Linux\*.
- Fixed issue with Maximum Non-Turbo Ratio.
- Fixed issue with A/C loss after removing power.
- Fixed issue with S3 and Intel® TXT.

#### BIOS Version 0047 - SWQ6710H.86A.0047.2011.0222.1058

#### About This Release:

- February 22, 2011
- ME Firmware: 5MB SKU 7.0.4.1197 Production
- MEBx Code: Based on Version 7.0.0.0053
- Integrated Graphics Option ROM: Build 2089 PC 14.34
- SATA RAID Option ROM: Intel(R) RAID for SATA v10.1.0.1008
- LAN Option ROM: Intel(R) Boot Agent GE v1.3.65

# New Fixes/Features:

- Fixed issue where the power button recovery is for cold boot path only.
- Fixed issue where provisioning record in Setup displays a "Setup IP" that is not correct.
- Updated Intel® ME firmware to the revision: 7.0.4.1197.
- Updated processor support.
- Added support for PCH B3 stepping.

BIOS Version 0041 - SWQ6710H.86A.0041.2011.0114.1542

## About This Release:

- January 14, 2011
- ME Firmware: 5MB SKU 7.0.2.1164 Production

\*Other names and brands may be claimed as the property of others.

- MEBx Code: Based on Version 7.0.0.0053
- Integrated Graphics Option ROM: Build 2089 PC 14.34
- SATA RAID Option ROM: Intel(R) RAID for SATA v10.1.0.1008
- LAN Option ROM: Intel(R) Boot Agent GE v1.3.65

# New Fixes/Features:

- Fixed issue where there is an additional shutdown with 95W processor warning message.
- Updated BIOS Setup to allow more characters to be displayed for SATA device model information.
- Revised Intel Standard Manageability Technology Configuration in Intel® ME menu.
- Fixed issue where optical drive name and solid state drive name does not show completely in Configuration > SATA, Boot > Optical Drive Order and Hard Drive Order lists in BIOS Setup.
- Updated BIOS Setup to show "Reset Intel Standard Manageability to default factory settings" for non-vPro processors in Maintenance mode.
- Hid VT-d and TXT in BIOS Setup when a non-vPro processor is installed.
- Fixed issue where operating system will not install via PXE with a hard drive or optical drive plugged into SATA ports 1 through 3.
- Fixed issue where EFI MEBx is not accessible after remote provisioning (bare metal/PKI method).
- Fixed issue where TXT S3 resume and BVT fail.
- Updated processor support.
- Hid Performance settings from Intel® Integrator Toolkit.
- Added SMBIOS programming for processor socket.

#### SWQ6710H.86A.0038.2010.1227.1958 Production BIOS

#### About This Release:

- December 27, 2010
- ME Firmware: 5MB SKU 7.0.2.1164 Production
- MEBx Code: Based on Version 7.0.0.0053
- Integrated Graphics Option ROM: Build 2089 PC 14.34
- SATA RAID Option ROM: Intel(R) RAID for SATA v10.1.0.1008
- LAN Option ROM: Intel(R) Boot Agent GE v1.3.65

#### New Fixes/Features:

- Updated ME F/W to the revision: 7.0.2.1164.
- Improved BIOS ID checking when using F7 BIOS Flash Update method.
- Fixed issue where boot order fails in RAID mode if inserting a bootable USB mass storage device into a USB port which is disabled in the setup.
- Changed default settings of PCH All-On Temperature and Control Temperature on DQ67EP.
- Added a warning message if a 95W TDP and above processor is installed on DQ67EP.

#### BIOS Version 0037 - SWQ6710H.86A.0037.2010.1222.1328

#### About This Release:

• December 22, 2010

- ME Firmware: 5MB SKU 7.0.0.1152 Production
- MEBx Code: Based on Version 7.0.0.0053
- Integrated Graphics Option ROM: Build 2089 PC 14.34
- SATA RAID Option ROM: Intel(R) RAID for SATA v10.1.0.1008
- LAN Option ROM: Intel(R) Boot Agent GE v1.3.65

#### New Fixes/Features:

- Added RCFG (Remote Configuration) option to Intel® ME page.
- Updated EFI MEBx reference code.
- Updated fan speed control related settings.
- Changed the warning message displayed when entering the wrong password while changing password on the Security page in BIOS setup.
- Corrected the status of Turbo Boost Technology on the Performance page if the processor does not support it.
- Corrected the unit of transfer-rate for optical drives on the SATA Drives page in BIOS setup.
- Corrected the unit of voltage for all voltage sensors on the Fan Control & Real-Time Monitoring page in BIOS setup.
- Fixed issue where system in the operating system if certain graphics cards are installed.
- Updated the maximum system memory support to 32GB in SMBIOS type 16.
- Fixed default settings of Over-Temperature Threshold, Control Temperature, and All-On Temperature to proper values for processor temperature.
- Fixed issue where system may halt during executing MEBx after updating SMBIOS with the specified data.
- Fixed issue where system may not boot on the first complete POST if the CMOS battery is removed.
- Fixed issue where wrong options are displayed in the Active Processor Cores setup item after selecting one value less than "All" on the 4-cores processor.
- Updated processor support.
- Fixed issue where system S3 resume fails when installing a graphics card on the PEG port (PCI-e x16 slot).
- Fixed issue where the integrated graphics display is abnormal if the IGD Primary Video Port is set to DVI-D and the IGD Secondary Video Port is set to None.
- Fixed issue where the bootup logo screen is corrupt when any prompt message/box shows during POST under RAID mode.
- Corrected HDD transfer-rate information in the SATA Drives page under RAID mode.
- Corrected the prompt text for +3.3v Standby.
- Fixed issue where the system will halt on the prompt message when changing the processor from Core i5/Core i7 to Core i3.
- Updated setup to hide the Intel® Turbo Boost Technology setup item if the processor does not support it.
- Changed the options of Active Processor Cores according to processor maximum core numbers.
- Changed the Front/Rear Fan Minimum Duty Cycle default value to 30.
- Updated ICC register locked mask.
- Changed CPU voltage value in SMBIOS type 4.

\*Other names and brands may be claimed as the property of others.

#### About This Release:

- December 4, 2010
- ME Firmware: 5MB SKU 7.0.0.1152 Production
- MEBx Code: Based on Version 7.0.0.0053
- Integrated Graphics Option ROM: Build 2089 PC 14.34
- SATA RAID Option ROM: Intel(R) RAID for SATA v10.1.0.1008
- LAN Option ROM: Intel(R) Boot Agent GE v1.3.65

# New Fixes/Features:

• Initial production BIOS release

# LEGAL INFORMATION

# Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries. Copyright (c) 2011 Intel Corporation.